

<u>Description</u>	<u>Project Status</u>	<u>Location</u>	<u>Cost Estimate</u>
Exterior Snow Guard	Existing	STJ	\$500
Security Cameras	Existing	STJ; OLOL	\$3,446
Metal Trim	Existing	STJ	\$10,000
Repair and seal parking lot and walkway	Completed	STJ	\$9,000
Insulate/sheetrock church interior walls	Existing	STJ	\$41,000
Weatherize big window facing road	Existing	STJ	\$2,000
Metal Exterior Doors	Existing	STJ	\$2,000
Resurface and Paint Concrete Steps	Completed	OLOL	\$400
Repair/seal large storm window on front of Saint Joseph's	In Process	STJ	\$1,900
Ice Dam Prevention	Existing	Parish Center	\$250
Rectory Bathroom Ventilation (Install vent fans- 3 bathrooms)	Existing	Rectory	\$750
Plumbing drainage issue (Rectory- Father's main bathroom)	Completed	Rectory	\$1,500
Repair driveway	Existing	OLOL	\$10,000
Relocate stairway from rear parking area (or redo railway on existing stairway)	Existing	OLOL	
Replace Aluminum siding with vinyl; cover wood trim with bent metal	Existing	OLOL	\$40,000
Paint or replace siding on road-facing side of Parish Center	Existing	Parish Center	\$1,000
Repair or replace concrete in garage (Rectory)	Existing	Rectory	\$1,000
Rectory Windows Repair (properly trim out, assuming no leakage has occurred)	Existing	Rectory	\$1,000
Repair foundation of OLOL church (repoint bricks)	Existing	OLOL	\$6,000
Commercial Refrigerator- 20 years old and constantly runs, repair or replace	Existing	Parish Center	\$5,000
Bathroom ceiling tiles, walls replaced under the urinals, new toilet in men's bathroom	Existing	Parish Center	\$1,000
Replace back door threshold in big room by kitchen	Existing	Parish Center	\$400
Replace roof	Existing	Rectory	\$7,000
Replace roof	Existing	OLOL	\$8,000
<b>Total Cost-</b>			<b>\$153,146</b>